

ABSTRACT

The implementation of Occupational Health and Safety Management System in a company is one way to bring out an Occupational Health and Safety aspect in order to realize a safety and productive work place. An optimal Occupational Health and Safety Management System operation can only be executed if there is a full support from the management of the company and active participation from the workers. Policy of PERTAMINA Marketing Unit V Surabaya to realize an aspect of Occupational Health and Safety in every operational activity is bring out with an implementation of SMK3LL entire the work zone, include Tanjung Perak Instalation. There is a method about assessment of SMK3LL, that is audit system, and internal audit is one of them. Result of internal audit can describe the effectivity of SMK3LL.in Tanjung Perak Instalation of PT.PERTAMINA (Persero) Marketing Unit V Surabaya.

The purpose of this research was to study the execution of SMK3LL and also to study each elemen of SMK3LL in Instalasi Tanjung Perak PT.PERTAMINA (Persero) U.Pms V Surabaya.

This research was a descriptive, observational and cross sectionally done. Primary data at this research is obtained with observation and interview used observation sheet. While secondary data is obtained from LK3 Tanjung Perak Instalation. Time of taking data is April'23rd – May'23rd 2007.

Result of this research described the implementation of SMK3LL in Instalasi Tanjung Perak PT.PERTAMINA (Persero) Marketing Unit V Surabaya was very good. Management had role to move worker in improving caring and civilizing aspect of K3LL continuously show commitments and support for K3LL effort.

To reach performance of SMK3LL better, there is something which still need to be improved. For the next, management of Tanjung Perak Instalation of PT.PERTAMINA (Persero) Marketing Unit V Surabaya have to review about program of K3LL in location continuously. Beside that, a measurement of work environmental factors have to do periodically by management.

Kata kunci : Execution of SMK3LL, Audit, Performance Evaluation of SMK3LL.

ABSTRAK

Penerapan SMK3 di perusahaan merupakan salah satu upaya melaksanakan aspek K3 dalam rangka mewujudkan lingkungan kerja yang produktif dan aman. SMK3 akan berjalan dengan baik apabila didukung oleh manajemen perusahaan dan partisipasi aktif dari tenaga kerja. Kebijakan PERTAMINA Unit Pemasaran V Surabaya untuk melaksanakan aspek K3 dalam setiap kegiatan operasi perusahaan, diwujudkan melalui penerapan SMK3LL di seluruh wilayah kerjanya, termasuk di Instalasi Tanjung Perak. Penilaian SMK3LL ini dilakukan dengan sistem audit, dan salah satunya adalah audit internal. Hasil audit tersebut dapat menggambarkan kinerja SMK3LL di Instalasi Tanjung Perak PT.PERTAMINA (Persero) U.Pms V Surabaya.

Tujuan penelitian ini adalah untuk mempelajari penerapan SMK3LL dan elemen SMK3LL di Instalasi Tanjung Perak PT.PERTAMINA (Persero) Unit Pemasaran V Surabaya.

Penelitian ini merupakan penelitian observasional yang bersifat deskriptif dan menurut waktunya merupakan penelitian *cross sectional*. Data primer diperoleh dari wawancara dan observasi. Sedangkan data sekunder diperoleh dari LK3 Instalasi Tanjung Perak PT.PERTAMINA (Persero) U.Pms V Surabaya. Waktu pengambilan data adalah 23 April 2007-23 Mei 2007.

Hasil penelitian ini menggambarkan bahwa kinerja SMK3LL di Instalasi Tanjung Perak PT.PERTAMINA (Persero) U.Pms V Surabaya telah mencapai kriteria sangat baik. Manajemen yang ada di lokasi memiliki peran untuk menggerakkan pekerja dalam meningkatkan kepedulian dan membudayakan aspek K3LL dengan terus-menerus menunjukkan komitmen dan memberikan dukungan terhadap upaya pembudayaan K3LL.

Untuk mencapai kinerja SMK3LL yang lebih baik lagi, ada beberapa hal yang masih perlu ditingkatkan. Untuk waktu yang akan datang, sebaiknya manajemen di Instalasi Tanjung Perak melakukan tinjauan ulang terhadap program K3LL yang sudah ada di lokasi. Selain itu perlu dilakukan pengukuran faktor lingkungan kerja secara berkala.

Kata kunci : Penerapan SMK3LL, Audit, Evaluasi Kinerja SMK3LL.